



Parking Lamp Bulb Upgrade

Classification	Repair Bulletin - Level I	Section/Group	17 - Electrical	Country/Region	North America
Year	2009 - 2011	Model	Roadster	Version	All

Bulletin Classification: *Repair Bulletin - Level I is released as instructions and guidelines to perform on the condition below or based on customer complaint. The information provided may not be VIN specific*

To enhance the operation and aesthetic appearance of the Roadster headlamp, an upgraded parking lamp bulb is now available. This optional accessory will increase the parking lamp illumination and project a cool white beam.

Procedure

1. Follow the Headlight Assembly – LH and Headlight Assembly – RH procedures in the service manual to remove both front headlight assemblies.
2. Place the headlight assemblies on a protective surface taking care not to scratch the outer lens surface.
3. Follow the Bulb - Side Light procedure in the service manual to remove the parking lamp bulb.

NOTE: The replacement bulb is brighter and has a cool white appearance when illuminated (Figure1).



OEM bulb installed



Upgraded bulb installed

Figure 1

4. Installation procedure is reverse of removal except for the following:
 - Check headlight to fender profiles and gaps.
 - Check and adjust headlight aim as necessary.

Affected Part(s) 1021199-00-A COOL WHITE WEDGE BULB
KIT-SB1317001-01 Complete Parts Kit

Affected VIN(s) As requested

Warranty/DMS Coding:

Description	Complaint	Cause	Correction
Install parking lamp bulbs, left and right side	A091	B053	S011317001

NOTE: Use Complete Kit Part Number for DMS parts entry only. Order parts separately listed above.