



Tesla, Inc.
2077 E University Drive
Tempe, AZ, US 85281
Ph.: 602-643-0024

Service Estimate

SERVICE DEPARTMENT HOURS

Mon-Fri 8:00 a.m. - 5:00 p.m.
Saturday-Sunday Sat 8am-4pm,
Sun: Closed

| | |
|--------------------|--------------------|
| Invoice date | Invoice number |
| ct-2021 | |
| Date/Time Received | Date/Time Promised |
| | |
| Odometer In | Odometer Out |
| 144584 Miles | Miles |
| Ready Date | |
| | |
| Service Advisor | |
| | |

| |
|---------|
| Bill To |
| |

| Mobile Phone | Additional Phone | | Vehicle Identification Number |
|--------------|------------------|----------------------|-------------------------------|
| <div></div> | <div></div> | | <div></div> |
| Year | Model | License Plate Number | Colour |
| 2017 | MODEL S | | Pearl White Multi-Coat Paint |

| Job Number | Description Of Work | Amount (USD) (USD) | | | | | |
|---|--|-----------------------|-----------------|-------------------|-----------------------|-------------------|-----------------|
| 1 | <div></div> Correction: Remote Diagnosis <div>Pay Type: Goodwill - Remote Support</div> | 0.00 | | | | | |
| | | | | | | | |
| 2 | <div></div> | 1,149.10 | | | | | |
| | | | | | | | |
| | Correction: General Diagnosis | | Price | Adjustment | Subtotal | | |
| | | | 82.50 | 0.00 | 82.50 | | |
| | Correction: A/C Compressor (2nd Generation) (Remove & Replace) | | Price | Adjustment | Subtotal | | |
| | | | 231.00 | 0.00 | 231.00 | | |
| | Parts Replaced or Added | | | | | | |
| | Part | | Quantity | Unit Price | Price | Adjustment | Subtotal |
| | A/C COMPRESSOR, ELECTRIC, NO RHVAC(1063369-00-J) | | 1.00 | 560.00 | 560.00 | 0.00 | 560.00 |
| | | | | | Parts Subtotal | 560.00 | |
| Correction: Receiver Dryer and Desiccant (Add Refrigerant Part if Needed) (Remove & Replace) | Price | Adjustment | Subtotal | | | | |
| | 264.00 | 0.00 | 264.00 | | | | |

| | | | | | | | |
|---|--|----------|------------|-------|------------|----------|------|
| | Parts Replaced or Added | | | | | | |
| | Part | Quantity | Unit Price | Price | Adjustment | Subtotal | |
| | Cap - Receiver and Drier(1007718-00-A) | 1.00 | 1.60 | 1.60 | 0.00 | 1.60 | |
| | Desiccant Bag - Subcool Condenser, 37g(1007717-00-A) | 1.00 | 10.00 | 10.00 | 0.00 | 10.00 | |
| | Parts Subtotal 11.60 | | | | | | |
| | Pay Type: Customer Pay | | | | | | |
| | Total Parts Amount 571.60 | | | | | | |
| | Total Labor Amount 577.50 | | | | | | |
| | Concern: Courtesy Inspection | | | | | | |
| 3 | Correction: Courtesy Inspection | | | | | | |
| | Pay Type: Goodwill - Service | | | | | | 0.00 |

3

Service Center hourly rate: USD 165

(3½ hours)

All parts are new unless otherwise specified.

You agree that: Tesla is not responsible for any personal items left in your vehicle; Tesla and its employees may access and operate your vehicle including on streets, highways, or public roadways for the sole purpose of testing and/or inspection of repairs; Tesla and its employees may access, download and use the information stored on your vehicle's data recorder to service and diagnose issues with your vehicle, and Tesla may store and aggregate such data for its own purposes; an express mechanic's lien is hereby acknowledged on your vehicle to secure the amount of repairs, storage and other applicable fees; the vehicle owner's insurance provides exclusive coverage for the vehicle while it is in Tesla's possession; and you may be charged storage fees of \$35/day from the fourth working day after you are notified that repairs on your vehicle are complete and that the vehicle is ready for pick up.

| | |
|---------------------------|-----------------|
| Total Parts (USD) | 571.60 |
| Total Labor (USD) | 577.50 |
| Discount | 0.00 |
| Subtotal (USD) | 1,149.10 |
| Tax | 46.30 |
| Total Amount (USD) | 1,195.40 |

Tesla disclaims all express or implied warranties with respect to any repairs or products used in repairs, except as may be set forth in your Tesla-issued New or Used Vehicle Limited Warranty, Tesla Parts, Body, and Paint Repair Limited Warranty or other extended service agreement. Tesla is not responsible for repairs not performed by, or components not installed by, Tesla. Any parts (including tires/wheels) removed or replaced by Tesla during vehicle service will become the property of Tesla. However, at the time you authorize repairs, you may request to receive (subject to any applicable core charge, which you agree to pay) or inspect replaced parts (excluding inflatable restraint system components), except body shop repair parts and parts required to be returned to the manufacturer or a third party under a warranty, trade-in or exchange agreement, which will only be presented to you for examination and not returned.

I authorize the repair work, including parts, materials and labor, on my vehicle to be done pursuant to the terms and conditions as set forth in this service agreement document.

Signature:**Date:****FullName:**

You further agree and acknowledge that:



Tesla, Inc.
19820 Hempstead Hwy
Houston, TX, US 77065
Ph.:

Service Estimate

SERVICE DEPARTMENT HOURS
Mon-Fri 0800 - 1800
Saturday-Sunday Sat 0800-1700, Sun
Closed

| Invoice date | Invoice number |
|--------------|----------------|
| | |

| Bill To |
|---------|
| |

| Mobile Phone | Additional Phone | | Vehicle Identification Number |
|--------------|------------------|----------------------|-------------------------------|
| | | | |
| Year | Model | License Plate Number | Colour |
| 2017 | MODEL S | | Pearl White Multi-Coat Paint |

| Job Number | Description Of Work | Amount (USD) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|--|---|--------------|----------|------------|----------|------------|----------|--|------|--------|--------|------|--------|--|------|------|------|------|------|------|----------|------------|-------|------------|----------|--|------|------|------|------|------|---|------|------|------|------|------|----------|
| 1 | <div></div> <div><div>Correction: A/C Compressor (Dual Motor) (Remove & Replace)</div><div><div>Price</div><div>Adjustment</div><div>Subtotal</div></div><div>408.500.00408.50</div><div>Parts Replaced or Added</div><table><thead><tr><th>Part</th><th>Quantity</th><th>Unit Price</th><th>Price</th><th>Adjustment</th><th>Subtotal</th></tr></thead><tbody><tr><td>A/C COMPRESSOR, ELECTRIC, NO RHVAC(1063369-00-H)</td><td>1.00</td><td>560.00</td><td>560.00</td><td>0.00</td><td>560.00</td></tr><tr><td>CBL TIE,44MM,4.6,PA66HS,UL94 V2,FIR TREE(1006855-00-A)</td><td>1.00</td><td>0.43</td><td>0.43</td><td>0.00</td><td>0.43</td></tr></tbody></table><div>Parts Subtotal 560.43</div><div>Correction: Receiver Dryer and Desiccant (Add Refrigerant Part if Needed) (Remove & Replace)</div><div><div>Price</div><div>Adjustment</div><div>Subtotal</div></div><div>354.750.00354.75</div><div>Parts Replaced or Added</div><table><thead><tr><th>Part</th><th>Quantity</th><th>Unit Price</th><th>Price</th><th>Adjustment</th><th>Subtotal</th></tr></thead><tbody><tr><td>Cap - Receiver and Drier(1007718-00-A)</td><td>1.00</td><td>2.31</td><td>2.31</td><td>0.00</td><td>2.31</td></tr><tr><td>Desiccant Bag - Subcool Condenser(1007717-00-A)</td><td>1.00</td><td>1.78</td><td>1.78</td><td>0.00</td><td>1.78</td></tr></tbody></table><div>Parts Subtotal 4.09</div><div>Correction: A/C Refrigerant Flush Due To Compressor Failure (Dual Motor) (NA)</div><div><div>Price</div><div>Adjustment</div><div>Subtotal</div></div></div> | Part | Quantity | Unit Price | Price | Adjustment | Subtotal | A/C COMPRESSOR, ELECTRIC, NO RHVAC(1063369-00-H) | 1.00 | 560.00 | 560.00 | 0.00 | 560.00 | CBL TIE,44MM,4.6,PA66HS,UL94 V2,FIR TREE(1006855-00-A) | 1.00 | 0.43 | 0.43 | 0.00 | 0.43 | Part | Quantity | Unit Price | Price | Adjustment | Subtotal | Cap - Receiver and Drier(1007718-00-A) | 1.00 | 2.31 | 2.31 | 0.00 | 2.31 | Desiccant Bag - Subcool Condenser(1007717-00-A) | 1.00 | 1.78 | 1.78 | 0.00 | 1.78 | 1,983.52 |
| Part | Quantity | Unit Price | Price | Adjustment | Subtotal | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| A/C COMPRESSOR, ELECTRIC, NO RHVAC(1063369-00-H) | 1.00 | 560.00 | 560.00 | 0.00 | 560.00 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| CBL TIE,44MM,4.6,PA66HS,UL94 V2,FIR TREE(1006855-00-A) | 1.00 | 0.43 | 0.43 | 0.00 | 0.43 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Part | Quantity | Unit Price | Price | Adjustment | Subtotal | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Cap - Receiver and Drier(1007718-00-A) | 1.00 | 2.31 | 2.31 | 0.00 | 2.31 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Desiccant Bag - Subcool Condenser(1007717-00-A) | 1.00 | 1.78 | 1.78 | 0.00 | 1.78 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

| | | | | | |
|---|--|---|------------------------------|--------|-------------|
| | | 655.75 | 0.00 | 655.75 | |
| | | | Pay Type: Customer Pay | | |
| | | Total Parts Amount 564.52 | | | |
| | | Total Labor Amount 1,419.00 | | | |
| | | Concern: Check tire pressure and condition | | | |
| | | Correction: Automated Tire Pressure Check | | | |
| 2 | | Correction: Checked Tire Tread Depth | | | |
| | | | Pay Type: Goodwill - Service | | 0.00 |

Service Center hourly rate: USD 215

(~6½ hours)

All parts are new unless otherwise specified.

You agree that: Tesla is not responsible for any personal items left in your vehicle; Tesla and its employees may access and operate your vehicle including on streets, highways, or public roadways for the sole purpose of testing and/or inspection of repairs; Tesla may update your vehicle's software in the course of a repair or as part of the standard vehicle maintenance process per your owner's manual and New Vehicle Limited Warranty; Tesla and its employees may access, download and use the information stored on your vehicle's data recorder to service and diagnose issues with your vehicle, and Tesla may store and aggregate such data for its own purposes; an express mechanic's lien is hereby acknowledged on your vehicle to secure the amount of repairs, storage and other applicable fees; the vehicle owner's insurance provides exclusive coverage for the vehicle while it is in Tesla's possession; and you may be charged storage fees of \$35/day from the fourth working day after you are notified that repairs on your vehicle are complete and that the vehicle is ready for pick up.

| | |
|---------------------------|-----------------|
| Total Parts (USD) | 564.52 |
| Total Labor (USD) | 1,419.00 |
| Discount | 0.00 |
| Subtotal (USD) | 1,983.52 |
| Tax | 46.58 |
| Total Amount (USD) | 2,030.10 |

Tesla disclaims all express or implied warranties with respect to any repairs or products used in repairs, except as may be set forth in your Tesla-issued New or Used Vehicle Limited Warranty, Tesla Parts, Body, and Paint Repair Limited Warranty or other extended service agreement. Tesla is not responsible for repairs not performed by, or components not installed by, Tesla. Any parts (including tires/wheels) removed or replaced by Tesla during vehicle service will become the property of Tesla. However, at the time you authorize repairs, you may request to receive (subject to any applicable core charge, which you agree to pay) or inspect replaced parts (excluding inflatable restraint system components), except body shop repair parts and parts required to be returned to the manufacturer or a third party under a warranty, trade-in or exchange agreement, which will only be presented to you for examination and not returned.

I authorize the repair work, including parts, materials and labor, on my vehicle to be done pursuant to the terms and conditions as set forth in this service agreement document.

Signature:

Date:

FullName:

You further agree and acknowledge that:

- Tesla is not responsible for loss or damage to the vehicle or any articles left in the vehicle in case of fire, theft, hail, wind, or any other causes beyond its control;
- Tesla personnel will turn off any photo or video capturing devices, such as dashboard cameras, once they receive the vehicle in preparation for service and your vehicle's Tesla dash cam will be enabled when you pick up your Tesla from this Service visit;