



Tesla, Inc.  
6142 Telegraph Rd  
Toledo, OH, US 43612  
Ph.:

## Service Estimate

**SERVICE DEPARTMENT HOURS**  
Mon-Fri 8:00 a.m. - 5:00 p.m  
Saturday-Sunday Sat-Sun: Closed

B.M.V.R.# 49690675

Invoice date	Invoice number
29-Aug-2022	3000-009-0007876883
Due Date	
29-Aug-2022	
Date/Time Received	Date/Time Promised
Odometer In	Odometer Out
Miles	Miles
Ready Date	
Service Advisor	

Bill To

Mobile Phone	Additional Phone	Vehicle Identification Number	
		5YJSA1AG9DFP11100	
Year	Model	License Plate Number	Colour
2013	MODEL S		Black

Job Number	Description Of Work	Amount (USD)																																												
1	<p><b>Concern:</b> Check tire pressure and condition</p> <p><b>Correction:</b> Checked Tire Tread Depth</p> <p><b>Correction:</b> Automated Tire Pressure Check</p> <p style="text-align: right;">Pay Type: Goodwill - Service</p>	0.00																																												
2	<p><b>Concern:</b> Rear brake pads are seized in calipers</p> <p><b>Correction: Brake Pads and Rotors - Rear - Set</b></p> <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th></th> <th>Price</th> <th>Adjustment</th> <th>Subtotal</th> </tr> </thead> <tbody> <tr> <td></td> <td style="text-align: right;">203.50</td> <td style="text-align: right;">0.00</td> <td style="text-align: right;">203.50</td> </tr> </tbody> </table> <p><b>Parts Replaced or Added</b></p> <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Part</th> <th>Quantity</th> <th>Unit Price</th> <th>Price</th> <th>Adjustment</th> <th>Subtotal</th> </tr> </thead> <tbody> <tr> <td>RR CALIPER SPRING AND PIN KIT(6008142-00-A)</td> <td style="text-align: right;">2.00</td> <td style="text-align: right;">32.00</td> <td style="text-align: right;">64.00</td> <td style="text-align: right;">0.00</td> <td style="text-align: right;">64.00</td> </tr> <tr> <td>REAR BRAKE PAD REPLACEMENT KIT - MANDO(1097416-00-B)</td> <td style="text-align: right;">1.00</td> <td style="text-align: right;">175.00</td> <td style="text-align: right;">175.00</td> <td style="text-align: right;">0.00</td> <td style="text-align: right;">175.00</td> </tr> <tr> <td>REAR BRAKE PAD SERVICE KIT(1068331-00-B)</td> <td style="text-align: right;">1.00</td> <td style="text-align: right;">195.00</td> <td style="text-align: right;">195.00</td> <td style="text-align: right;">0.00</td> <td style="text-align: right;">195.00</td> </tr> <tr> <td>REAR BRAKE ROTOR - RASSINI(1027632-00-B)</td> <td style="text-align: right;">2.00</td> <td style="text-align: right;">165.00</td> <td style="text-align: right;">330.00</td> <td style="text-align: right;">0.00</td> <td style="text-align: right;">330.00</td> </tr> <tr> <td>BLT CSK TRX M8X1.25X20 10.9-ZNAL-W(1004377-00-B)</td> <td style="text-align: right;">2.00</td> <td style="text-align: right;">0.43</td> <td style="text-align: right;">0.86</td> <td style="text-align: right;">0.00</td> <td style="text-align: right;">0.86</td> </tr> </tbody> </table>		Price	Adjustment	Subtotal		203.50	0.00	203.50	Part	Quantity	Unit Price	Price	Adjustment	Subtotal	RR CALIPER SPRING AND PIN KIT(6008142-00-A)	2.00	32.00	64.00	0.00	64.00	REAR BRAKE PAD REPLACEMENT KIT - MANDO(1097416-00-B)	1.00	175.00	175.00	0.00	175.00	REAR BRAKE PAD SERVICE KIT(1068331-00-B)	1.00	195.00	195.00	0.00	195.00	REAR BRAKE ROTOR - RASSINI(1027632-00-B)	2.00	165.00	330.00	0.00	330.00	BLT CSK TRX M8X1.25X20 10.9-ZNAL-W(1004377-00-B)	2.00	0.43	0.86	0.00	0.86	1,265.54
	Price	Adjustment	Subtotal																																											
	203.50	0.00	203.50																																											
Part	Quantity	Unit Price	Price	Adjustment	Subtotal																																									
RR CALIPER SPRING AND PIN KIT(6008142-00-A)	2.00	32.00	64.00	0.00	64.00																																									
REAR BRAKE PAD REPLACEMENT KIT - MANDO(1097416-00-B)	1.00	175.00	175.00	0.00	175.00																																									
REAR BRAKE PAD SERVICE KIT(1068331-00-B)	1.00	195.00	195.00	0.00	195.00																																									
REAR BRAKE ROTOR - RASSINI(1027632-00-B)	2.00	165.00	330.00	0.00	330.00																																									
BLT CSK TRX M8X1.25X20 10.9-ZNAL-W(1004377-00-B)	2.00	0.43	0.86	0.00	0.86																																									

						<b>Parts Subtotal 764.86</b>
	<b>Correction: Brake Caliper - Rear - LH - Brembo (Remove &amp; Replace)</b>	<b>Price</b>	<b>Adjustment</b>	<b>Subtotal</b>		
		148.00	0.00	148.00		
	<b>Correction: Brake Caliper - Rear - RH - Brembo (Remove &amp; Replace)</b>	<b>Price</b>	<b>Adjustment</b>	<b>Subtotal</b>		
		148.00	0.00	148.00		
	<b>Parts Replaced or Added</b>					
	<b>Part</b>	<b>Quantity</b>	<b>Unit Price</b>	<b>Price</b>	<b>Adjustment</b>	<b>Subtotal</b>
	BOLT,TE,M12-1.75x45, [109],G0110[B],SMAT(1088969-00-B)	2.00	0.59	1.18	0.00	1.18
						<b>Parts Subtotal 1.18</b>
						Pay Type: Customer Pay
	<b>Total Parts Amount</b>	<b>766.04</b>				
	<b>Total Labor Amount</b>	<b>499.50</b>				
<b>3</b>	<b>Concern:</b> Automated tire pressure check; tire pressure adjustment recommended					
	<b>Correction: Set Tire Pressure</b>					
						Pay Type: Goodwill - Service
						<b>0.00</b>

Service Center hourly rate: USD 185

All parts are new unless otherwise specified.

You agree that: Tesla is not responsible for any personal items left in your vehicle; Tesla and its employees may access and operate your vehicle including on streets, highways, or public roadways for the sole purpose of testing and/or inspection of repairs; Tesla may update your vehicle's software in the course of a repair or as part of the standard vehicle maintenance process per your owner's manual and New Vehicle Limited Warranty; Tesla and its employees may access, download and use the information stored on your vehicle's data recorder to service and diagnose issues with your vehicle, and Tesla may store and aggregate such data for its own purposes; an express mechanic's lien is hereby acknowledged on your vehicle to secure the amount of repairs, storage and other applicable fees; the vehicle owner's insurance provides exclusive coverage for the vehicle while it is in Tesla's possession; and you may be charged storage fees of \$35/day from the fourth working day after you are notified that repairs on your vehicle are complete and that the vehicle is ready for pick up.

Total Parts (USD)	766.04
Total Labor (USD)	499.50
Discount	0.00
<b>Subtotal (USD)</b>	<b>1,265.54</b>
Tax	98.08
<b>Total Amount (USD)</b>	<b>1,363.62</b>

Tesla disclaims all express or implied warranties with respect to any repairs or products used in repairs, except as may be set forth in your Tesla-issued New or Used Vehicle Limited Warranty, Tesla Parts, Body, and Paint Repair Limited Warranty or other extended service agreement. Tesla is not responsible for repairs not performed by, or components not installed by, Tesla. Any parts (including tires/wheels) removed or replaced by Tesla during vehicle service will become the property of Tesla. However, at the time you authorize repairs, you may request to receive (subject to any applicable core charge, which you agree to pay) or inspect replaced parts (excluding inflatable restraint system components), except body shop repair parts and parts required to be returned to the manufacturer or a third party under a warranty, trade-in or exchange agreement, which will only be presented to you for examination and not returned.