

Report Details

Number: 8532019

Date: Apr 30, 2023

Status: Complete

Reference: 5198



Vehicle History Report for 5YJSA1E27GF153962



VIN:

5YJSA1E27GF153962



Vehicle:

2016 Tesla Model S



Assembled:

TESLA, INC.



Vehicle Age:

7 years



Rental Usage

No



Total Owners

1




Last Odometer

14951



Accident Count

0



Last Title State

CO



Odometer Problems

No



Detailed Vehicle History



Historical Owner Records



No Auctions & Incidents



No NHTSA Recalls



No Historical Sales Listings



Vehicle Specifications



Prior Vehicle Usage



Personal



Fleet



Rental



Lease



Taxi



Police














Government



Commercial


Detailed Vehicle History

Historical events for this vehicle listed in chronological order. International records are not available.

Date	Mileage	Source	Details
2016		Original Manufacturer	Manufactured in TESLA, INC.
09/17/2016		MOTOR VEHICLE DEPARTMENT	REGISTRATION ISSUED OR RENEWED
10/28/2016		MOTOR VEHICLE DEPARTMENT	TITLE
04/09/2018		MOTOR VEHICLE DEPARTMENT	REGISTRATION ISSUED OR RENEWED
02/29/2020		MOTOR VEHICLE DEPARTMENT	REGISTRATION ISSUED OR RENEWED
08/10/2020		MOTOR VEHICLE DEPARTMENT	EMISSION INSPECTION
02/10/2021		MOTOR VEHICLE DEPARTMENT	TITLE (TITLE #:004843564)
02/10/2021		MOTOR VEHICLE DEPARTMENT	REGISTRATION ISSUED OR RENEWED
01/15/2022		MOTOR VEHICLE DEPARTMENT	REGISTRATION ISSUED OR RENEWED
01/27/2023		MOTOR VEHICLE DEPARTMENT	REGISTRATION ISSUED OR RENEWED

Historical Owner Records

 **Purchase Year:** 2016

 **Status:** Current

 **Date Range:** 09/2016

 **Location:** CO

Vehicle Specifications

Specifications

Vehicle Descriptor 5YJSA1E2*GF	Make TESLA	Manufacturer Name TESLA, INC.	Model Model S	Model Year 2016
Plant City FREMONT	Vehicle Type PASSENGER CAR	Plant Country UNITED STATES (USA)	Plant State CALIFORNIA	Body Class Hatchback/Liftback/N
Doors 5	Bed Type Not Applicable	Cab Type Not Applicable	Trailer Type Connection Not Applicable	Trailer Body Type Not Applicable
Steering Location Left-Hand Drive (LHD)	EV Drive Unit Dual Motor	Engine Model 3 Phase A/C Induction (Dual Motor)	Fuel Type - Primary Electric	Electrification Level BEV (Battery Electric Vehicle)
Seat Belt Type Manual	Other Restraint System Info Type 2 Manual seatbelts (FR, SR*3), PODS	Front Air Bag Locations 1st Row (Driver and Passenger)	Knee Air Bag Locations 1st Row (Driver and Passenger)	Side Air Bag Locations 1st Row (Driver and Passenger)
NCSA Body Type 5-door/4-door hatchback	NCSA Make Other Domestic Manufacturers	NCSA Model Tesla	Bus Floor Configuration Type Not Applicable	Bus Type Not Applicable
Custom Motorcycle Type Not Applicable	Motorcycle Suspension Type Not Applicable	Motorcycle Chassis Type Not Applicable		

Stolen Vehicle Check

Check for Theft & Fraud Records	VIN: 5YJSA1E27GF153962	
---	-------------------------------	---

Supplemental Resources Recommended sources and services for finding out more about this vehicle.

Recommendation	Requires	Source
Check for Deactivated Airbag Records	VIN: 5YJSA1E27GF153962	
Check this Vehicle's 5-star Safety Ratings	Year, Make, Model	
Check this Vehicle's Retail Value	Year, Make, Model	
Order a Full Vehicle Inspection	Service Fee: \$109.95+	
Compare this Vehicle's Insurance Quotes	Driver + Vehicle Information	
Browse Similar For-Sale Listings	Zip Code + Vehicle Information	



Exterior

- Windshield free of cracks
- Body panel colors match
- Magnet adheres to all steel body panels
- Fresh paint job (if yes, it could be to conceal rust)
- Seams where the trunk and hood close are properly aligned
- Seams where doors and fenders meet are properly aligned
- Free of body scratches
- Free of body dents
- Windshield wipers and blades fully functional
- Headlights and directional lights intact and fully functional

Tires

- Tires are a reputable brand name (Michelin, Bridgestone, Goodyear)
- Tires are all of the same make
- Tires are free of any cuts, bubbles or cracks
- Tread worn evenly (uneven wear indicates alignment and suspension problems)
- Spare tire, jack and lug wrench on car and fully functional
- Spare tire inflated

Engine

- Free of fluid or oil leaks
- Oil filler neck not coated with thick, black deposits
- Battery terminals free of corrosion
- Oil dip stick free of dark, black oil
- Free of odors while engine is running
- Exhaust pipe emissions are neither blue (indicates engine burns oil) or black (indicate excessive oil consumption)

Suspension

- Vehicle rests levelly
- When bouncing the vehicles corners, no creaking noises are made
- All corners respond the same when bouncing

Interior

- Seats unworn and free of cracks
- All doors open and close freely
- Trunk opens and closes freely
- Lacks a heavy scent of air freshener (may indicate something is being concealed)
- All gauges work
- No dashboard warning lights remain illuminated
- Stereo works
- Heater works
- Air conditioner works
- Windshield wipers work
- Windshield wiper fluid dispenses properly

- All seats equipped with functional seat belts
- All seats adjust properly
- Power windows operate properly
- Sunroof opens and closes properly (if applicable)
- Car alarm works (if applicable)
- Trunk and driver-side door lock and unlock with key
- Hazard lights function properly
- Headlights, including brights, work properly

Frame

- Chassis is neither bent nor cracked
- No signs of crumpling or straightening inside the trunk
- Frame holes just inside outer edge clean and free of scratches

Automatic Transmission

- Transmission fluid looks clean, not dirty or gritty (no indicates possible internal transmission problem)
- Transmission neither slips nor delays when driving

Manual or Standard Transmission

- Each gear shifts smoothly
- No grinding noises when in reverse

Brakes

- Vehicle steers straight and does not pull to one side when applying brakes
- Parking brake engages and disengages freely
- No grinding noises when applying brakes
- Wheels do not lock when applying antilock brakes (if applicable)

Steering

- Vehicle does not drift to one side without prodding
- Vehicle is stable; no shaking or vibrating
- No resistance in the steering wheel when turning
- No clicking or clunking when turning

Miscellaneous

- Car manual located in the glove compartment
- Instructions included for any accessories
- Service and repair records available
- Owner has title

[Print Checklist](#)